



A DIVISION OF GETZ FIRE EQUIPMENT

**Getz Equipment Innovators
Part No.: 3G0112
Cylinder Drying Enclosure**



2320 Lakecrest Drive, Pekin, Illinois 61554
Telephone: 888-747-4389 Fax: 309-495-0625
Website: www.getzequipment.com

EQUIPMENT INNOVATORS

Limited Warranty

Products manufactured by Getz Equipment Innovators (with exception of electrical products or components) will be free from defects for a period of one year from shipment date. Electrical products and/or components used in manufactured products will have a (6) month warranty from shipment date. During the warranty period, customers who experience any manufacture-related service issues with our products, the product may be returned for repair or replacement. Customer must contact Getz Equipment for approval prior to any product return. Notwithstanding the foregoing, the limited warranty set forth shall be immediately void of customer uses any replacement parts other than those provided by Getz Equipment Innovators. The warranty does not cover normal wear and tear items, defects resulting from modification, alteration, misuse, exposure to corrosive conditions, extremely high temperatures, improper installation or maintenance. Warranties on component items not manufactured by Getz Equipment Innovators are provided by others whose warranty, evaluation and judgment will be final.

All implied warranties, including, but not limited to, warranties of fitness for purpose and merchantability, are limited to the time periods as stated above. In no event shall Getz Equipment Innovators be liable to incidental or consequential damages. Some states do not allow limitations on how long an implied warranty lasts or the exclusions or limitation of incidental or consequential damages, so that the above limitations or exclusions may not apply to you. Getz Equipment Innovators neither assumes nor authorizes any representative or other person to assume for it any obligation or liability other than as expressly set forth herein.

Mobile Service Vehicles:

The warranty does not cover:

- Defects in the chassis and or power unit
- Defects in separately manufactured products not produced by Getz Equipment Innovators
- Deterioration due to normal wear, tear, and exposure
- Repairs made necessary by negligent use, misuse, abuse, loading the service vehicle beyond its gross vehicle weight limitations, accident, acts of God, or other contingencies beyond the control of Getz Equipment Innovators.
- Repairs deemed necessary by reason of the failure to follow ordinary maintenance procedures.
- Repairs deemed necessary by reason of alterations done without Getz Equipment Innovators' written approval.

Warranty Service:

- All warranty repairs will be performed by Getz Equipment Innovators in Pekin, IL, unless otherwise authorized by Getz Equipment Innovators.

Freight:

- Getz Equipment Innovators will not be liable for shipping or transportation charges to or from customer's location.

This warranty gives you specific legal rights, and you may also have other rights which vary from state to state. To obtain performance to the obligation of the warranty, write to Getz Equipment Innovators, 2320 Lakecrest Drive, Pekin IL 61554, USA for instructions.

**Getz Equipment Innovators
Cylinder Drying Enclosure (3G0112)**

Table of Contents

Page

3 Setup & Operating Instructions
4 Parts List
4 Trouble Shooting

Getz Equipment Innovators (3G0112)

Power Source/Unit Location:

A 120AC 20 AMP dedicated circuit is required.

Dryer enclosure must be kept at least 6" away from any wall, to allow for proper ventilation and air flow.

Safety Requirements:

Safety Glasses

Protective gloves are recommended. Cylinders can reach a temperature of 150 degrees Fahrenheit

Operating Instructions:

1. Turn dryer switch on approximately half hour before needing to dry your first cylinder.
2. Before putting cylinders into the dryer make sure they are completely empty of water. A Getz Hydro-Aid will help remove as much water as possible before drying, speeding up the drying time of the cylinder.
3. Put the cylinder over the air exhaust tubes.
4. After approximately 20 minutes check the cylinder with an internal inspection light to verify all water has been completely removed. Hand protection may be needed as the cylinder may reach a temp of 150 F. If the cylinder is not dry place back into the dryer for additional drying time.
5. Replace the air filter element every 6 months or sooner if necessary.

Parts List

Part Number	Description
1G0499	Caster
1G0496	Blower motor
1G0498	Heating element
1G0179	Stainless Hinge
1G0497	Thermostat
1G0515	Air filter

Trouble Shooting

<u>Issue</u>	<u>Solution</u>
Air temperature is cold	Heating element is not operating correctly Part number 1G0498 Thermostat is not operating correctly Part number 1G0497
There is no air flow	Blower is not operating correctly Part number 1G0496 Switch is not operating correctly Part number 1G0494 Filter is full of media – replace Part number 1G0515